

DATE: 18 August 2023

CYCLE: 2308, Effective 10 August 2023 to 06 September 2023

SUBJECT: Incorrect turn direction

DESCRIPTION

Garmin has been made aware that the following procedure was delivered with an incorrect turn direction:

Airport	Procedure	Error
4V0	ELIZZ ONE DEPARTURE (ELIZZ1)	Upon departure from RWY 07, the correct turn direction should be a left turn direct ELIZZ.

This Data Alert applies to the 2308 cycle of the Garmin Navigation Database. This Data Alert does not apply to the Jeppesen NavData database.

PILOT ACTION

Do not use the procedure in any manner.

RESOLUTION

The procedure will be corrected in the 2309 cycle of the Garmin Navigation Database.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE GARMIN NAVIGATION DATABASE

Garmin requests that the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to fly.garmin.com and select "Aviation Data Error Report."