



JEPPESEN[®]
NavData[®] Alert

!! URGENT !!

Date: 14 September 2023

Subject: Nabire, Indonesia
Douw Aturure (WABI)
VOR Rwy 16, RNP Rwy 17, RNP Rwy 35
Cycle 2309

Procedure missing from database/ procedures deleted

Jeppesen NavData for cycle 2309, effective 7 September 2023 contains incorrect data for Douw Aturure; Nabire, Indonesia (WABI). INDONESIA - SUP 037-23 - 07 SEP 23 has been received too late to be processed. Procedure **VOR Rwy 16** is missing from database, procedures **RNP Rwy 17** and **RNP Rwy 35** should not be used.

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO
APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

Revised coding will appear in Jeppesen NavData for cycle 2310, effective 5 October 2023. Until then an entry will appear in the NavData Change, and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#). Please refer to the Chart Alert posted on the Jeppesen Web site: [Notices and Alerts](#) for valid information.

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:
+1-303-328-4445 (Western Hemisphere)
+49 610 250 8175 (Eastern Hemisphere)
E-mail: navdatasupport@boeing.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.

WABI_2309