



**JEPPESEN<sup>®</sup>**  
**NavData<sup>®</sup> Alert**

**!! URGENT !!**

**Date:** 13 October 2023  
**Subject:** Culiacan, Mexico  
Culiacan Intl (MMCL)  
RNP Rwy 02  
Cycle 2310

***Procedure missing from database***

Jeppesen NavData for cycle 2310, effective 5 October 2023, contains incorrect data for Culiacan Intl; Culiacan (MMCL). NOTAM A8567/23 was received after the ICAO specified date for aeronautical information publication.

Instrument approach procedure **RNP Rwy 02 is missing from database.**

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

Revised coding will appear in Jeppesen NavData for cycle 2311, effective 2 November 2023. Until then an entry will appear in the NavData Change Notices and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:  
+1-303-328-4445 (Western Hemisphere)  
+49 610 250 8175 (Eastern Hemisphere)  
E-mail: [navdatasupport@boeing.com](mailto:navdatasupport@boeing.com)

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.