



**JEPPESEN<sup>®</sup>**  
**NavData<sup>®</sup> Alert**

**!! URGENT !!**

**Date:** 6 October 2023  
**Subject:** Brazil  
Enroute Waypoint  
Cycle 2310

***Incorrect coordinates for Enroute Waypoint***

Jeppesen NavData for cycle 2310, effective 5 OCT 2023 contains incorrect coordinates for the on airway Enroute Waypoint MOLVA within Brazil. The correct coordinates for MOLVA should be **S21 57.3 W045 32.3**.

MOLVA is used on RNAV Airways Z47 and Z55. The corresponding bearing and distance information for both airways in 2310 navdata is correct per source.

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO  
APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

Revised coding will appear in Jeppesen NavData for cycle 2311, effective 2 NOV 2023. Until then an entry will appear in the NavData Change Notices, and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:  
+1-303-328-4445 (Western Hemisphere)  
+49 610 250 8175 (Eastern Hemisphere)  
E-mail: [navdatasupport@boeing.com](mailto:navdatasupport@boeing.com)

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.

MOLVA waypoint 2310