



!! URGENT !!

Date: 29 November 2023

Subject: Lorient, France
Lann-Bihoué (LFRH)
Multiple procedures
Cycle 2312

Procedure coding outdated

Jeppesen NavData for cycle 2312, effective 30 November 2023, contains incorrect data for Lann-Bihoué; Lorient, France (LFRH). France MIL AMDT 13/23, EFF 30 NOV 23 was received after the ICAO specified date for aeronautical information publication.

ILS Y Rwy 27 and LOC Y Rwy 25: Lorient LOR (TAC) approach transition: Outbound course from LOR (TAC) should read **057 degrees**.

TACAN Rwy 07: Lorient LOR (TAC) approach transition: Outbound course from LOR (TAC) should read **268 degrees**.

TACAN Rwy 25: Lorient LOR (TAC) approach transition: Outbound course from LOR (TAC) should read **057 degrees**.

RNP Rwy 20: should not be used.

RNAV STARs ARE 1N [ARE1N], BAGAD 1N [BAGA1N], LENSU 1N [LENS1N], QPR 1N [QPR1N] should not be used.

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised coding will appear in Jeppesen NavData for cycle 2313, effective 28 December 2023. Until then an entry will appear in the NavData Change Notices and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:
+1-303-328-4445 (Western Hemisphere)
+49 610 250 8175 (Eastern Hemisphere)
E-mail: navdatasupport@boeing.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.