

!! URGENT !!

Date: 22 December 2023

Subject: Venezuela Venezuela ATS System Cycle 2313

Airway coding outdated

Jeppesen data for cycle 2313, effective 28 December 2023, contains incorrect data for Venezuela ATS system listed below. VENEZUELA - AMDT 007-23 AIRAC - 28 DEC 23 was received after the ICAO specified date for aeronautical information publication.

LOWER ATS ROUTES

A300 waypoint HENRY should read OPMEB, LDP VOR should read CRP XONIM (044140.00N, 0610146.00W) A550 waypoint HENRY should read OPMEB, waypoint ERICA removed from airway, segment BNS VOV - CTN VOR 129/57°, 98 NM, FL95-FL245 Class C A552 waypoint GUADA should read DIDUB G300 waypoint BABOR should read EDVOP G431 segment EMAPA - ALCOT added 232/52 Deg, FL30-FL245 Class E G678 LDP VOR should read CRP XONIM (044140.00N, 0610146.00W), TERSI should read SUMBI W1 GOLFO should read EDMIG W2 TORTU should read EPKAD W3 GUADA should read DIDUB W5 KERON should read RELIX W7 Directions of cruising levels changed, GNA VOR - CBL lower limit should read FL50, CBL VOR - SFD VOR lower limit should read FL90, SFD VOR - CAIPE lower limit should read FL160, TIGRE - VRA VOR lower limit should read FL30, VRA VOR - MAR VOR lower limit should read FL40 W8 EVG - LFA distance should read 42 NM W11 GUADA should read DIDUB, RODOK should read UMGIB, JENDE should read NEKUS W14 LIMAS should read SULKI W18 LIMAS should read SULKI If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at: +1-303-328-4445 (Western Hemisphere)

+49 610 250 8175 (Eastern Hemisphere) E-mail: navdatasupport@boeing.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.

W19 TORTU should read EPKAD
W20 LDP VOR should read CRP XONIM (044140.00N, 0610146.00W)
W24 KERON should read RELIX, RODOK should read UMGIB
W40 RODOL should read ILREG, JENDE should read NEKUS

UPPER ATS ROUTES

UA550 HENRY should read OPMEB,

UA551 ONGAL - ALDIT bearings should read 250/70°.

UG442 NUXUL MIQ changed to NUXUL - IVROV CRP 124°, 9 NM, FL250-UNL Class A odd levels, IVROV CRP - MIQ 124°, 41NM, FL250-UNL Class A odd levels

UG443 AGNIL renamed to ESMEN, segment BNA - VURAN - ANGIL changed to BNA - UTLIB CRP (095710N 0640115W) 117/297°, 41 NMM lower limit FL245, mea FL50 Class A, UTLIB - ESMEN 117/298°, 35 NM lower limit FL 245 MEA FL50 class A.

UW1 GOLFO should read EDMIG

UW14 NEDEX should read ILNOL

UW20 USOMI (092720N 0644449W) should read UTKEG (092211N 0652801W), GEMAP - UTKEG CRP 144/324°, 65 NM, UTKEG - SOM VOR 145/325°, 39 NM, altitudes and airspace class unchanged **UW27** DAVBA renamed OPKAT, OROSU (091902N 0645239W) should read KUGLU (091531N 0644602W). OPKAT - KUGLU CRP 131/311°, 51 NM, KUGLU - SOM VOR 131/312°, 41 NM, altitudes and airspace class unchanged

UW50 NEDEX should read ILNOL

UW52 DABEX should read NUXOV

AREA NAVIGATION ROUTES (RNAV)

UL219 NIKPA (104909N 0632705W) changed to KOKBU (104540.00N, 0630843.00W), segment MTA - NIKPA - MEGIR changed to MTA - KOKBU CRP 115/295°, 49NM, KOKBU - MEGIR 115/296°, 77NM altitudes and class unchanged

UL304 segment MIDUR - OPSEN changed to MIDUR OPTUB CRP (113433N 0664455W) 158/338° 30NM, OPTUB - OPSEN 158/338°, DAVBA renamed OPKAT, TEPER changed to IROPI (085600N 0650656W), OPKAT - Iropi 164/334°, 49NM, IROPI - BIXUS 164/345 degrees, 112 NM. altitudes and airspace class unchanged

UL325 BURGA changed to NCRP

UL337 ALDIT coordinates should read 124748N 0634534W

UM796 new segment added (MAU VOR/ISIGO 271°/91° 26NM; ISIGO/MAR VOR 271°/91° 14NM)

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at: +1-303-328-4445 (Western Hemisphere) +49 610 250 8175 (Eastern Hemisphere)

E-mail: navdatasupport@boeing.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.

NAME CODE DESIGNATORS FOR SIGNIFICANT POINTS

Coordinates of waypoint changed: ALDIT 124710N 0634450W should read 124748N 0634534W

Below waypoints are missing from database:

DIDUB - 103517N 0692919W EDMIG - 110113N 0711211W EDVOP - 075511N 0722825W EPKAD - 105342N 0651843W ILREG - 094729N 0695837W NEKUS - 093556N 0702642W RELIX - 101518N 0683624W SULKI - 100214N 0660411W SUMBI - 062105N 0621701W UBLAK - 091527N 0602546W UMGIB - 101950N 0695058W UMPIB - 091058N 0601952W XONIM - 044140N 0610146W

Below waypoints should not be used:

BABOR ERICA GOLFO GUADA JENDE KERON LIMAS RODOK RODOL TERSI TORTU

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised coding will appear in Jeppesen NavData for cycle 2401, effective 25 January 2024. Until then an entry will appear in the NavData Change Notices and this Alert will be posted on the Jeppesen Web site: Notices and Alerts.

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at: +1-303-328-4445 (Western Hemisphere) +49 610 250 8175 (Eastern Hemisphere) E-mail: <u>navdatasupport@boeing.com</u>

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.