



## !! URGENT !!

**Date:** 18 August 2023

**Subject:** Luang Phabang, Laos  
Luang Phabang Intl (VLLB)  
STAR NTH (NTH1B)  
STAR NTH (NTH2B)  
SID NTH (NTH1A)  
SID NTH (NTH2A)  
Cycle 2308

### *Procedure identifiers incorrect*

Jeppesen NavData for cycle 2308, effective 10 August 2023, contains incorrect data for Luang Phabang Intl; Luang Phabang, Laos (VLLB). AIP AMDT 001-23 – 30 JUL 23 was received after the ICAO specified date for aeronautical information publication.

NTH waypoint replaced by LNT VOR/DME:

Arrival procedure NTH [NTH1B] should read **LNT [LNT1B]**  
Arrival procedure NTH [NTH2B] should read **LNT [LNT2B]**  
Departure Procedure NTH [NTH1A] should read **LNT [LNT1A]**  
Departure Procedure NTH [NTH2A] should read **LNT [LNT2A]**

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

Revised coding will appear in Jeppesen NavData for cycle 2309, effective 7 September 2023. Until then an entry will appear in the NavData Change Notices and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:  
+1-303-328-4445 (Western Hemisphere)  
+49 610 250 8175 (Eastern Hemisphere)  
E-mail: [navdatasupport@boeing.com](mailto:navdatasupport@boeing.com)

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.

VLLB\_2308