

FliteCharts Data Alert

TO: Users of all Garmin aviation products and Garmin Pilot™ using the United States or North America FliteCharts® database

DATE: October 3, 2023

CYCLE: 2310

SUBJECT: RNAV (GPS) RWY 27, AMDT 1A at General Edward Lawrence Logan Intl, Boston, MA (BOS)

DESCRIPTION

The FAA has advised Garmin that the digital-Terminal Procedures Publications, effective October 5, 2023, did not apply the Amendment 1A changes for RNAV (GPS) RWY 27 at General Edward Lawrence Logan Intl (KBOS), Boston, MA. The chart was incorrectly published as RNAV (GPS) RWY 27, AMDT 1.

The original safety alert can be seen at the following link:

https://www.faa.gov/air_traffic/flight_info/aeronav/safety_alerts/media/TERM_23-04_SA_BOS_R27.pdf

PILOT ACTION

Exercise caution when referencing the RNAV (GPS) RWY 27 chart at General Edward Lawrence Logan Intl (KBOS), Boston, MA with United States or North America FliteCharts for cycle 2310.

Alerts are written for the currently effective cycle and next cycle. It is possible that data from prior cycles is also affected. Garmin recommends using the latest effective data cycle.

RESOLUTION

The chart will be corrected in cycle 2311 of the United States and North America FliteCharts databases for applicable Garmin aviation products and in Garmin Pilot. Cycle 2311 FliteCharts databases are effective November 2, 2023 and will be available October 31, 2023.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE US OR NORTH AMERICA FLITECHARTS DATABASE

Garmin requests that the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to fly.garmin.com and select "[Aviation Data Error Report](#)."