

# FliteCharts Data Alert

**TO:** Users of all Garmin aviation products and Garmin Pilot using the Australia FliteCharts database

**DATE:** November 07, 2023

**CYCLE:** 2311

**SUBJECT:** CORRECTION TO SUNSHINE COAST AIRPORT (YBSU) EXPANSION PROJECT: MAIN APRON AND TWY M REALIGNMENT

---

## **DESCRIPTION**

Airservices Australia has advised Garmin that some charts at Sunshine Coast (YBSU), Queensland, Australia included in FliteCharts cycle 2311, effective November 2, 2023, do not depict changes to the Main Parking Apron, TWY M, and new TWY B3 as part of the construction of Bays 19, 19A, 20, and 20A. Revised charts have been published in SUP H80/23, effective October 26, 2023.

The following charts are affected:

- AERODROME CHART PAGE 1
- AERODROME CHART PAGE 2
- APRON CHART - PAGE 1
- APRON CHART - PAGE 2

The original AIP supplement can be seen at the following link:

<https://www.airservicesaustralia.com/aip/current/sup/s23-h80.pdf>

## **PILOT ACTION**

Exercise caution when referencing the above charts associated with Sunshine Coast (YBSU), Queensland, Australia in Australia FliteCharts for cycle 2311.

## **RESOLUTION**

Updated charts will be available in the 2312 cycle, effective November 30, 2023, of the Australia FliteCharts databases for applicable Garmin aviation products and in Garmin Pilot.

**THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE AUSTRALIA FLITECHARTS DATABASE**

*Garmin requests that the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to [fly.garmin.com](https://fly.garmin.com) and select "[Aviation Data Error Report](#)."*