

FliteCharts Data Alert

TO: Users of all Garmin aviation products and Garmin Pilot™ using the United States or North America FliteCharts® database

DATE: December 11, 2023

CYCLE: 2312

SUBJECT: Missing Data on ILS OR LOC RWY 4, at Quincy RGNL-Baldwin FLD, Quincy, IL (UIN)

DESCRIPTION

The FAA has advised Garmin that the digital-Terminal Procedures Publication, effective November 30, 2023, is missing data on the ILS OR LOC RWY 4 chart at Quincy Rgnl-Baldwin Fld, Quincy, IL (KUIIN).

The original safety alert can be seen at the following link:

https://www.faa.gov/air_traffic/flight_info/aeronav/safety_alerts/media/TERM_23-07_SA_UIN_IL4.pdf

PILOT ACTION

Exercise caution when referencing affected charts ILS OR LOC RWY 4 and LOC RWY 4 at Quincy Rgnl-Baldwin Fld (KUIIN), Quincy, IL with United States or North America FliteCharts for cycle 2312.

Alerts are written for the currently effective cycle and next cycle. It is possible that data from prior cycles is also affected. Garmin recommends using the latest effective data cycle.

RESOLUTION

The charts will be corrected in cycle 2313 of the United States and North America FliteCharts databases for applicable Garmin aviation products and in Garmin Pilot. Cycle 2313 FliteCharts databases are effective December 28, 2023 and will be available December 26, 2023.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE US OR NORTH AMERICA FLITECHARTS DATABASE

Garmin requests that the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to fly.garmin.com and select "[Aviation Data Error Report](#)."