

## !! URGENT !!

Date: 22 February 2024

Subject: Macao, PR of China Macao Intl (VMMC) ILS X Rwy 34 VOR DME Rwy 34

## Procedure coding incorrect

Jeppesen NavData for cycle 2402, effective 22 February 2024, contains incorrect data for Macao Intl; Macao, PR of China (VMMC).

ILS X Rwy 34: Coordinates of D184G should read N22 08.1 E113 35.9 VOR DME Rwy 34: Missed approach: crossing altitude of at or above 3940' should be placed at D12.6 MCU.

## WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised coding will appear in Jeppesen NavData for cycle 2403, effective 21 March 2024. Until then an entry will appear in the NavData Change Notices and this Alert will be posted on the Jeppesen Web site: <u>Notices and Alerts</u>.

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at: +1-303-328-4445 (Western Hemisphere) +49 610 250 8175 (Eastern Hemisphere) E-mail: navdatasupport@boeing.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.