

GARMIN®

Navigation Data Alert 26048

TO: Users of the Garmin Navigation Database
DATE: April 30, 2026
CYCLE: 2604
SUBJECT: Spain Enroute Fixes in Wrong Location

PRODUCT AFFECTED

Cycle 2604 of the Garmin Navigation Database (effective April 16, 2026) is affected.



NOTE

This Data Alert does not apply to the Jeppesen NavData database.

DESCRIPTION

The following Spain enroute fixes are wrong.

Table 1. Spain Enroute Fixes

| Fix Ident | Country | Correction | Usage |
|------------------|----------------|---|------------------------------------|
| PIR03 | Spain | The correct longitude for PIR03 is E002-30-00 | Exclusive military use enroute fix |
| PIR04 | | The correct longitude for PIR04 is E004-10-00 | Exclusive military use enroute fix |
| PIR05 | | The correct longitude for PIR05 is E004-40-00 | Exclusive military use enroute fix |

PILOT ACTION

Do not use the affected fixes.

RESOLUTION

The fixes will be corrected in the 2605 cycle of the Garmin Navigation Database.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE GARMIN NAVIGATION DATABASE

Garmin requests the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to FlyGarmin.com and select "Aviation Data Error Report."