



!! URGENT !!

Date: 4 September 2023

Subject: Ingolstadt, Germany
Manching (ETSI)
Multiple procedures
Cycle 2309

Procedure coding outdated

Jeppesen NavData for cycle 2309, effective 7 September 2023, contains incorrect data for Manching; Ingolstadt, Germany (ETSI). CENOR FLIP VOL 2 - 07 SEP 23 was received after the ICAO specified date for aeronautical information publication.

Below procedures should **not** be used:

- ILS Z or LOC RWY 24L,
- ILS Y or LOC RWY 24L,
- NDB Z RWY 24L,
- NDB Y RWY 24L,
- Copter N NDB RWY 24L

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised coding will appear in Jeppesen NavData for cycle 2310, effective 5 October 2023. Until then an entry will appear in the NavData Change Notices and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:
+1-303-328-4445 (Western Hemisphere)
+49 610 250 8175 (Eastern Hemisphere)
E-mail: navdatasupport@boeing.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.