

DATE: 15 September 2023

CYCLE: 2309, Effective 07 SEP 2023 to 04 OCT 2023

SUBJECT: Incorrect Altitude on Missed Approach

DESCRIPTION

Garmin has been made aware that the following procedure was delivered with an incorrect altitude on the initial climb on the missed approach:

Airport	Procedure	Error
KMQY	RNAV (GPS) RWY 32 (R32)	The missed approach initial climb should be at or above 1500 ft prior to turning.

This Data Alert applies to the 2309 cycle of the Garmin Navigation Database. This Data Alert does not apply to the Jeppesen NavData database.

PILOT ACTION

Use the procedure with extreme caution.

RESOLUTION

The procedure will be corrected in the 2310 cycle of the Garmin Navigation Database.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE GARMIN NAVIGATION DATABASE

Garmin requests that the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to fly.garmin.com and select "Aviation Data Error Report."