

FliteCharts Data Alert

TO: Users of all Garmin aviation products and Garmin Pilot using the Australia FliteCharts database
DATE: December 04, 2023
CYCLE: 2312
SUBJECT: BRISBANE (YBBN) RWY 01R AND RWY19L TEMPORARY APPROACH PROCEDURES

DESCRIPTION

Airservices Australia has advised Garmin that the RNP S RWY 19L (AR) chart at Brisbane (YBBN), Queensland, Australia included in FliteCharts cycle 2312, effective November 30, 2023, does not have a caution note. A revised chart has been published in SUP H88/23, effective November 30, 2023.

The original AIP supplement can be seen at the following link:

<https://www.airservicesaustralia.com/aip/current/sup/s23-h88.pdf>

PILOT ACTION

Exercise caution when referencing the RNP S RWY 19L (AR) chart associated with Brisbane (YBBN), Queensland, Australia in Australia FliteCharts for cycle 2312.

Alerts are written for the currently effective cycle and next cycle. It is possible that data from prior cycles is also affected. Garmin recommends using the latest effective data cycle.

RESOLUTION

The chart will be corrected in cycle 2313 of the Australia FliteCharts databases for applicable Garmin aviation products and in Garmin Pilot. Cycle 2313 FliteCharts databases are effective December 28, 2023 and will be available December 26, 2023.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE AUSTRALIA FLITECHARTS DATABASE

Garmin requests that the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to fly.garmin.com and select "[Aviation Data Error Report](#)."