

FliteCharts Data Alert

TO: Users of all Garmin aviation products and Garmin Pilot™ using the United States or North America FliteCharts® database

DATE: February 21, 2024

CYCLE: 2401 and 2402

SUBJECT: RNAV (GPS) RWY 14, RNAV (GPS) RWY 32 and ALTERNATE MINIMUMS, at Perry Muni, Perry, IA (PRO)

DESCRIPTION

The FAA has advised Garmin that the digital-Terminal Procedures Publications, effective January 25, 2024 and February 22, 2024, contain suspended charts at Perry Muni (KPRO), Perry, IA. The suspended charts are RNAV (GPS) RWY 14, RNAV (GPS) RWY 32, and the associated ALTERNATE MINIMUMS.

The original safety alert can be seen at the following link:

https://www.faa.gov/air_traffic/flight_info/aeronav/safety_alerts/media/TERM_24-01_SA_KPRO.pdf

PILOT ACTION

Do not use the RNAV (GPS) RWY 14, RNAV (GPS) RWY 32, and ALTERNATE MINIMUMS charts at Perry Muni (KPRO), Perry, IA with United States or North America FliteCharts for cycles 2401 and 2402.

Alerts are written for the currently effective cycle and next cycle. It is possible that data from prior cycles is also affected. Garmin recommends using the latest effective data cycle.

RESOLUTION

The charts will be corrected in cycle 2403 of the United States and North America FliteCharts databases for applicable Garmin aviation products and in Garmin Pilot. Cycle 2403 FliteCharts databases are effective March 21, 2024 and will be available March 19, 2024.

THIS ALERT SHOULD BE MADE AVAILABLE TO ALL USERS OF GARMIN AVIATION UNITS OR SYSTEMS UTILIZING THE US OR NORTH AMERICA FLITECHARTS DATABASE

Garmin requests that the flight crew report any observed discrepancies related to database information. These discrepancies could come in the form of an incorrect procedure, incorrectly identified terrain, obstacles, fixes, or any other displayed item used for navigation or communication in the air or on the ground. Go to fly.garmin.com and select "[Aviation Data Error Report](#)."